



Wind Mill **W1**

	ückliste/Ersatzteilliste ndmühle W1	Bill of material Windmill W1			
	d/Nr. Benennung No. Part No.	Abm. Bemerk. Diment. Remarks	Stück Pieces	Denomination	
1 2 3 4 5	Windmühl-Haus Windmühl-Rad Achse Achse mit Einstich Sicherungsscheibe	Ø 4x75mm Ø 4x67mm 3,2mm	1 1 1 1	Windmill house Windmill aheel Axle Axle Look washer	
6 7 8 9 10	Kugellager Distanzbüchse Distanzbüchse Mitnehmer Riemenrad	Ø 11x4mm Ø 6x4x8mm Ø 6x4x3mm Ø 12x9mm Ø 39,2x8mm	4 2 1 1 2	Ball bearing Main shaft Belt pulley Carrier Belt pulley	
11 12 13 14 15	O-Riemen Antrieb O-Riemen Antrieb Madenschraube Linsenkopfschraube Holzbrett	Ø110x1,5mm Ø45x1,5mm M3x3 SW1,5 M3x4 TX10	1 1 3 1 1	Belt drive Belt drive Grub screw Torx screw Beech base	
16 17 18 19	Typenschild W1 Gummifüße Scheibe Senkschraube	Ø12x1,5mm M4x20mm TX20	1 3 2 2	Typ plate Rubber foot Washer Counter-sunk screw	

Please inspect all parts before you start assembling the kit set as we can not accept any returns if the model has been partly or fully assembled.

For technical advice, please contact us: www.rarecreations.co.nz



11.10.2014